



4550 Jackson Street Denver, CO 80216
FAX (303) 355-3516 / (800) 447-8326
Internet - <http://www.steamway.com>

1992-1999 Technical Bulletins

For More Information, Contact Steam Way International at (303) 355-3566

Revised - January 2000

Technical Bulletin Index (1992-2000)

List Of Technical Bulletins

<u>Reference Number</u>	<u>Subject/Description</u>
TB 92 1	The Role Of Cleaning and Maintenance In The Reduction Of Biological Contamination In Carpeting
TB 92 2	Carpet and Its Positive Contributions To The Total Indoor Environment
TB 92 3	The Case Against Fresh Water Rinsing In Carpet Cleaning
TB 93 4	Using High Temperature Hot Water Extraction Carpet Cleaning - Its Advantages & Benefits
TB 93 5	Waste Water Disposal
TB 92 6	What Is The Biggest Problem In The Carpet Cleaning Business?
TB 92 7	Carpet Cleaning Methods Report
TB 92 8	Marketing Cigarette Smoke Deodorization Services
TB 92 9	Misconceptions About Acid Spotting Solutions
TB 92 10	Sanitizing Principles For The Cleaner & Restorer
TB 92 11	The Carpet Cleaning Industry and Sick Building Syndrome
TB 92 12	The High Cost Of "Free" Heat
TB 92 13	New Carpet and Indoor Air Quality
TB 93 14	Understanding Fabric Protectors
TB 93 15	Principles Of Improving Indoor Air Quality Through Carpet Cleaning
TB 93 16	Simplifying Fabric Protectors
TB 91 17	Kawasaki Syndrome and Carpet Cleaning
TB 93 18	The Problem With Acid Rinsing In Carpet Cleaning
TB 93 19	Carpet Filtration Soiling
TB 93 20	Disaster Restoration
TB 93 21	Bloodborne Pathogens Standard - A Simplified Summary
TB 92 22	Carbon Monoxide and Your Cleaning Equipment
TB 93 23	Problem Carpets and How To Deal With Them
TB 92 24	Sick Building Syndrome and Cleaning
TB 93 25	Suggested Guidelines For Remediation Of Sewage Damage
TB 94 26	Basic Procedures For Upholstery Cleaning
TB 94 28	Deodorization Solutions For Water Damage Are Developing Rapidly
TB 94 29	Technology Improvements In Truck Mounts Finally Extend Beyond New Components
TB 94 30	Rocket Science Applied To Truck Mounts
TB 94 31	A Straightforward Approach To Upholstery Cleaning
TB 94 32	The Milliken - Capture Connection, What's A Cleaner To Do
TB 94 33	Ceiling Cleaning - A Profitable Future In Looking Up

TB 93	34	A Competitive Environment Demands More From Suppliers
TB 94	35	Specialized Complex Carpet Cleaning Problems
TB 91	36	Are You Getting "Steamed" About Carpet Cleaning?
TB 94	37	Successful Carpet Spotting
TB 94	38	Pressure Washing For The Cleaner & Restorer
TB 91	39	A Simple Approach To Cleaning Stain Resistant Carpets
TB 94	40	Deodorization and Odor Control Services
TB 95	41	Disaster Avoidance Planning
TB 95	42	Another Look At Yellowing
TB 95	43	Marketing Deodorization Services
TB 95	44	Truck Mount Heating System Alternatives
TB 95	45	Marketing Pet Odor Deodorization Services
TB 95	46	Commercial Carpet Cleaning
TB 96	47	Truck Mount Vacuum Systems
TB 96	48	Carpet Spotting Spotting Success Analysis
TB 97	49	Chemical Sensitivity Analysis
TB 97	50	The Olefins Are Amongst Us
TB 98	51	Hot Cleaning Units - A Truck Mount Performance Measurement Mechanism
TB 99	52	Proper Application Techniques For Solvent-Carried Fabric Protectors

Distributor Order Form:

Please send 1 copy of each circled Technical Bulletin to:

Distributor Name _____

Company Name _____

Address _____

City, State, Zip _____

Phone _____

Fax _____

Please return order form by mail or fax to:

Eloise Castaneda
 Steam Way International, Inc.
 4550 Jackson Street
 Denver, CO 80216

Fax (303) 355-3516